



Power supply is on the far end of an 8in cable connected to J1 and J5.

J2, J3, J4, J6, J7 Feed individual ODD on the far end of 24in cables. The far end is typically the hot-swap connection.

THE MATERIAL AND PROCESS IN WHICH THIS COMPONENT IS PRODUCED SHALL MEET EUROPEAN DIRECTIVE 2002/95/EC (RoHS), RIMAGE QMS1010 SUPPLIER QUALITY MANUAL, AND RIMAGE QMS1020 RESTRICTED HAZARDOUS SUBSTANCES SPECIFICATION.

THESE DRAWINGS AND SPECIFICATIONS ARE THE PROPERTY OF RIMAGE CORP. AND SHALL NOT BE USED OR REPRODUCED FOR ANY PURPOSE WITHOUT WRITTEN PERMISSION.



R I M A G E™

(c) Rimage Corporation
7725 Washington Ave. So. Mpls MN 55439

Title PCBA, ODD HOT-SWAP		
Size B	Document Number 2003184	Rev 0
Date: 04/23/14 12:47:14	Sheet 1	of 1