

TAS2562HYFPR – Debug Update




Conclusion:


For GREG OC issue, FA performed on the Good unit and NG unit for comparison, it is confirmed no physical difference & defect, no contamination, as further evidence to support no long term reliability risk which proved by early technical explanation and bench test results

Units	TI Status	Comments	Customer Status
7 units	GREG/OC Issue	TI provided resolution. Screen Identified and added if required	Screen tested and accepted by customer.

Top metal




Good unit




NG unit

Inner Metal layer

GREG
Circuit




Good unit




NG unit

Poly



Good unit



NG unit