




ICBOOST INCIDENCE

MMWAVEICBOOST + DCA1000EVM + IWR6843ISK





SOP name	Setting
SOP2	OFF
SOP1	ON
SOP0	ON



Switch name	Setting when connect with DCA
S1.12	ON
S1.11	ON
S1.10	ON
S1.9	OFF
S1.8	OFF
S1.7	OFF
S1.6	OFF
S1.5	ON
S1.4	OFF
S1.3	ON
S1.2	ON
S1.1	OFF

5V, 2.5 A, DC
Power Supply


Switch to
"DC_JACK_5V_IN"



Ethernet Cable

Micro USB

5V, 2.5 A, DC
Power Supply



▼ Puertos (COM y LPT)

- AR-DevPack-EVM-012 (COM10)
- AR-DevPack-EVM-012 (COM11)
- AR-DevPack-EVM-012 (COM8)
- AR-DevPack-EVM-012 (COM9)
- Serie estándar sobre el vínculo Bluetooth (COM12)
- Serie estándar sobre el vínculo Bluetooth (COM13)
- XDS110 Class Application/User UART (COM22)
- XDS110 Class Auxiliary Data Port (COM23)



[RadarAPI]: MSSFWVersion:(00.00.00.00 (00/00/00))



▼ Puertos (COM y LPT)

- AR-DevPack-EVM-012 (COM10)
- AR-DevPack-EVM-012 (COM11)
- AR-DevPack-EVM-012 (COM8)
- AR-DevPack-EVM-012 (COM9)
- Serie estándar sobre el vínculo Bluetooth (COM12)
- Serie estándar sobre el vínculo Bluetooth (COM13)

```
BSS power up done async event received!  
[RadarAPI]: Status: Passed  
[RadarAPI]: ar1.GetMSSFWVersion()  
[RadarAPI]: MSSFWVersion:(00.00.00.00 (00/00/00))  
[RadarAPI]: ar1.GetBSSFWVersion()  
[RadarAPI]: BSSFWVersion:(00.00.00.00 (00/00/00))  
[RadarAPI]: Warning: BSS firmware version Mismatch!
```

Status: Failed, Error Type: RESP TIMEOUT