

REVISIONS		DATE	BY	OP
REV	DESCRIPTION	DATE	BY	OP
1.	ADD AISACFVAL 100nf+47nf			
2.	CMLOUTP/NV0XFAHQ*8E-08*1*0 61E-81			
3.	3.22C-05U0-8			
4.	6.00TAC-pin36-R4307/R4311LISE-6-R4312/			
5.	CAN_GPIOL/2x-W00ohm			
6.	C4140-05U6-A10-05-A1			
	SAMPLE B			
7.	DB05P-change COM_FSC_SQU/SBA	08/20		
	SAMPLE C			
8.	add R4127/R4132, link pin45/17 to SOC	10/09		
9.	add R4133/R4134, pull up pin 15/17 to 0.9VIO	10/09		
10.	change R4138/R4139/R4141/R4112/R4114/R4115 to			
11.	change R4138/R4139/R4141/R4112/R4114/R4115 to			
12.	change R4138/R4139/R4141/R4112/R4114/R4115 to			
13.	change R4138/R4139/R4141/R4112/R4114/R4115 to			
14.	Downgrade L4150/L4151/L4152/L4154/L4155/L4156 to	11/25		
15.	change L4150/L4151/L4152/L4154/L4155/L4156 to	12/21		
16.	DB05P C4145/R4132/C4152	3/1		
17.	delete DB05P of R4102/R4103/R4104	3/1		
18.	delete DB05P of R4101	3/29		
19.	delete R4108/R4109/R4112/R4109/R4111/000000pin	000000pin		

