




TUSB8042A_BOM_LIST

A. POWER_BLOCK


- 1- C25_C31/ C33_C36 - C1005X7R1C104K050BC
- 2- C32,C37 - CL05A106MQ5NUNC
- 3- U5 - TPS2560DRCR
- 4- R35-R36,R43 - ERA-2AEB103X
- 5- R41 - ERA-2AEB2552X
- 6- C40,C43,C45,C54,C55 - CL05B104KA5NNNC
- 7- C44,C46 - GRM21BR60J107ME15L
- 8- U6 - S-13A1C11-U5T1U3
- 9- C51,C56 - C1005X5R0J225M050BC
- 10- C55 - C1005C0G1H102J050BA
- 11- F10 - 782631222

B. USB 3.0 PORTS

1. R28 - ERA-2ARB9531X
2. R30 - ERA-2AEB103X
3. R31 - ERA-2AEB9092X
4. C38 - CL05A106MP8NUB8
5. C23,C24 - C0603X5R1E104K030BB
6. R29,R40,R44 - ERA-2AEB472X
7. C39,C41,C51,C52 - C0603X5R1E104K030BB
8. C42,C57 - CL05B104KA5NNNC
9. F9,F11 - BBHV00160808601Y00
10. D23_D34 - SP3208-01UTG

C. CLOCK, RESET AND MISC

1. R32,R33,R34,R37,R38,R39 - ERA-2AEB472X
2. R42 - ERJ-2RKF1004X
3. C47,C48 - C0402C120C5GAC7867
4. X1 - Q 24,0-JXS22-12-10/15-T1-FU-WA-LF



USB_UP_STREAM_PROTECTION_BOM_LIST

- 1- D10_D15 - SP3208-01UTG
- 2- F5_F6 - 744233670
- 3- F7 - 744232090