

Eye/Mask Mode

Eye Meas

Extinction Ratio

Mask Test


Jitter RMS

Jitter p-p

Average Power

Crossing Percentage

More (1 of 3)



Measure

	current	minimum	maximum	total meas
Rise time(1)	97.8 ps	95.6 ps	97.8 ps	443
Fall time(1)	86.7 ps	86.7 ps	88.9 ps	443
Jitter p-p(1)	40.00 ps	22.22 ps	40.00 ps	443

Setup & Info

Eye/Mask Mode

Eye Meas

Extinction Ratio

Mask Test

Jitter RMS

Jitter p-p


Average Power

Crossing Percentage

More (1 of 3)

RZ

NRZ



Measure

	current	minimum	maximum	total meas
Rise time(1)	95.6 ps	93.3 ps	95.6 ps	196
Fall time(1)	88.9 ps	82.2 ps	88.9 ps	196
Jitter p-p(1)	35.56 ps	20.00 ps	35.56 ps	196

Setup & Info

Eye/Mask Mode

Eye Meas

Extinction Ratio

Mask Test

Jitter RMS


Jitter p-p

Average Power

Crossing Percentage

More (1 of 3)

RZ NRZ



Measure

	current	minimum	maximum	total meas
Rise time(1)	93.3 ps	91.1 ps	95.6 ps	164
Fall time(1)	88.9 ps	84.4 ps	88.9 ps	164
Jitter p-p(1)	42.22 ps	17.78 ps	42.22 ps	164

Setup & Info

Eye/Mask Mode

Eye Meas

Extinction Ratio

Mask Test

Jitter RMS


Jitter p-p

Average Power

Crossing Percentage

More (1 of 3)

RZ NRZ



Measure

	current	minimum	maximum	total meas
Rise time(1)	93.3 ps	93.3 ps	100.0 ps	130
Fall time(1)	86.7 ps	86.7 ps	88.9 ps	130
Jitter p-p(1)	35.56 ps	24.44 ps	35.56 ps	130

Setup & Info

