

Reverse loopback

When there is no packer error,
IDEL ERROR occur at MAC I/F of DP83867.

When there is packer error,
IDEL ERROR occur at MDI or link perter PHY.

