



don't PD SMBUS

missing Vbus switch here

<USB_HUB>

Title:	_____	Designer:	_____
Document Number:	R4013-M0024-01	Document Version:	0.2
Assembly PIN:	R4052-G0005-01	Date:	2023-05-05
Sheet:	66 of 75		