



Waveform of TPS2552

Good IC waveform



problem

In the problem IC, V_{fault} pin falls to L.

I do not know the cause.

Even if it is verified with TPS2552DRV1EVM - 364, it also becomes the waveform of the problem.

As a result of verification with ATE, it becomes a good product.

Question

- What's the problem?