




Replaced with 5K Pot attached with valve and a series trim pot value 10K for Zero adjustment

LM136 2.5V Ref



LM324 Cost effective



10K TrimPot for Span Adjustment

