




- **CRU Description:**

Unit#1: no voice

- **FA Result:**

Unit#1 is observed damage and cannot do any further analysis.





Conclusion:

Unit#1 was damaged at power supply or GND metal line or inner circuit, so the unit would possibly fail as no voice, low voice, or no output.

There is no symmetrical risk and we will continually monitor this device quality.