



SN74LV123A circuit



In case of Pulse width 60mSec ($R_t = 620K$, $C_t = 0.1\mu\text{Sec}$)

Irregular behavior happened



In case of Pulse width 30mSec ($R_t = 310K$, $C_t = 0.1\mu\text{Sec}$)

Normal behavior happened

