

USB analyzer log when a problem occurs
A log when a key code failure is detected about 100 hours after continuous operation of the keyboard.



