





























Left installed via Resource Exp - Rt installed via C2000Ware Updater

Produced: 7/11/2024 3:16:04 PM

Mode: Differences

Left base folder: C:\ti\C2000Ware_5_02_00_00

Right base folder: C:\ti\c2000\C2000Ware_5_02_00_00

| Name | Size | Modified | Name | Size | Modified |
|---|-----------|----------------------|--|-------------|----------------------|
|  .metadata | 8,775,248 | 7/11/2024 3:09:21 PM |  .metadata | 2,324,490 | 4/10/2024 6:12:31 PM |
|  boards | 2,783,095 | 7/11/2024 3:10:23 PM |  boards | 405,124,550 | 4/10/2024 6:04:22 PM |
| | | |  .meta | 2,783,095 | 4/10/2024 6:12:23 PM |
|  boosterpack_json_files | 102,676 | 7/11/2024 3:10:23 PM | | | |
|  components | 66,876 | 7/11/2024 3:10:23 PM | | | |
| | | |  controlCARDS | 304,113,596 | 4/10/2024 6:04:22 PM |
| | | |  controlSTICKS | 2,602,929 | 4/10/2024 6:04:20 PM |
| | | |  ExperimenterKits | 25,403,550 | 4/10/2024 6:04:22 PM |
|  images | 1,994,350 | 7/11/2024 3:10:23 PM | | | |
| | | |  LaunchPads | 65,831,994 | 4/10/2024 6:04:20 PM |
| | | |  PeripheralExplorerKits | 1,025,393 | 4/10/2024 6:04:21 PM |
|  templates | 11,558 | 7/11/2024 3:10:23 PM | | | |
| | | |  TIDesigns | 3,363,993 | 4/10/2024 6:04:22 PM |
|  BOOSTXL_EXAMPLE.syscfg.json | 2,770 | 7/11/2024 3:10:23 PM | | | |
|  BOOSTXL-3PhGaNInv.syscfg.json | 4,904 | 7/11/2024 3:10:23 PM | | | |
|  BOOSTXL-BUCKCONV.syscfg.json | 3,168 | 7/11/2024 3:10:23 PM | | | |
|  BOOSTXL-CANFD-LIN.syscfg.json | 4,290 | 7/11/2024 3:10:23 PM | | | |
|  BOOSTXL-DRV3245AQ1.syscfg.json | 7,543 | 7/11/2024 3:10:23 PM | | | |
|  BOOSTXL-DRV8301.syscfg.json | 5,784 | 7/11/2024 3:10:23 PM | | | |
|  BOOSTXL-DRV8305EVM.syscfg.json | 5,846 | 7/11/2024 3:10:23 PM | | | |
|  BOOSTXL-DRV8320RS.syscfg.json | 5,829 | 7/11/2024 3:10:23 PM | | | |
|  BOOSTXL-DRV8323Rx.syscfg.json | 7,981 | 7/11/2024 3:10:23 PM | | | |
|  BOOSTXL-ETHERCAT.syscfg.json | 3,644 | 7/11/2024 3:10:23 PM | | | |
|  BOOSTXL-POSMGR.syscfg.json | 5,597 | 7/11/2024 3:10:23 PM | | | |
|  BOOSTXL-POSMGR-NEW.syscfg.json | 6,184 | 7/11/2024 3:10:23 PM | | | |
|  BOOSTXL-SHARP128.syscfg.json | 3,047 | 7/11/2024 3:10:23 PM | | | |

| | | | | | |
|--|--------|----------------------|--|--|--|
| _cc_f2838x_board.syscfg | 343 | 7/11/2024 3:10:23 PM | | | |
| _cc_f28002x_board.syscfg | 344 | 7/11/2024 3:10:23 PM | | | |
| _cc_f28003x_board.syscfg | 344 | 7/11/2024 3:10:23 PM | | | |
| _cc_f28004x_board.syscfg | 344 | 7/11/2024 3:10:23 PM | | | |
| _cc_f28379d_board.syscfg | 343 | 7/11/2024 3:10:23 PM | | | |
| _cc_f2800157_board.syscfg | 344 | 7/11/2024 3:10:23 PM | | | |
| _DRV8300RDGE-EVM.syscfg.json | 5,947 | 7/11/2024 3:10:23 PM | | | |
| _DRV8311HEVM.syscfg.json | 5,852 | 7/11/2024 3:10:23 PM | | | |
| _DRV8316REVM.syscfg.json | 6,640 | 7/11/2024 3:10:23 PM | | | |
| _DRV8328AEVM.syscfg.json | 7,143 | 7/11/2024 3:10:23 PM | | | |
| _DRV8329AEVM.syscfg.json | 7,143 | 7/11/2024 3:10:23 PM | | | |
| _LaunchPad_component_tracking.xlsx | 10,443 | 7/11/2024 3:10:23 PM | | | |
| _LAUNCHXL_F28P55X.syscfg.json | 37,150 | 7/11/2024 3:10:23 PM | | | |
| _LAUNCHXL_F28P65X.syscfg.json | 41,720 | 7/11/2024 3:10:23 PM | | | |
| _LAUNCHXL_F28379D.syscfg.json | 25,081 | 7/11/2024 3:10:23 PM | | | |
| _LAUNCHXL_F280025C.syscfg.json | 32,043 | 7/11/2024 3:10:23 PM | | | |
| _LAUNCHXL_F280039C.syscfg.json | 35,451 | 7/11/2024 3:10:23 PM | | | |
| _LAUNCHXL_F280049C.syscfg.json | 32,841 | 7/11/2024 3:10:23 PM | | | |
| _LAUNCHXL_F2800137.syscfg.json | 25,219 | 7/11/2024 3:10:23 PM | | | |
| _LAUNCHXL_F2800157.syscfg.json | 29,986 | 7/11/2024 3:10:23 PM | | | |
| _lp_f28002x_board.syscfg | 346 | 7/11/2024 3:10:23 PM | | | |
| _lp_f28003x_board.syscfg | 346 | 7/11/2024 3:10:23 PM | | | |
| _lp_f28003x_board_with_bp.syscfg | 404 | 7/11/2024 3:10:23 PM | | | |
| _lp_f28003x_board_with_bp_added.syscfg | 941 | 7/11/2024 3:10:23 PM | | | |
| _lp_f28004x_board.syscfg | 346 | 7/11/2024 3:10:23 PM | | | |
| _lp_f28004x_board_with_bp.syscfg | 404 | 7/11/2024 3:10:23 PM | | | |
| _lp_f28379d_board.syscfg | 345 | 7/11/2024 3:10:23 PM | | | |
| _lp_f280015x_board.syscfg | 346 | 7/11/2024 3:10:23 PM | | | |
| _lp_f2800137_board.syscfg | 346 | 7/11/2024 3:10:23 PM | | | |
| _TMDSCNCD28P55X.syscfg.json | 24,227 | 7/11/2024 3:10:23 PM | | | |
| _TMDSCNCD28P65X.syscfg.json | 32,459 | 7/11/2024 3:10:23 PM | | | |
| _TMDSCNCD28379D.syscfg.json | 28,150 | 7/11/2024 3:10:23 PM | | | |

| | | | | | |
|-----------------------------|--------|----------------------|----------------------|-----------|----------------------|
| TMDSCNCD28388D.syscfg.json | 32,369 | 7/11/2024 3:10:23 PM | | | |
| TMDSCNCD280025C.syscfg.json | 21,705 | 7/11/2024 3:10:23 PM | | | |
| TMDSCNCD280039C.syscfg.json | 22,232 | 7/11/2024 3:10:23 PM | | | |
| TMDSCNCD280049C.syscfg.json | 21,292 | 7/11/2024 3:10:23 PM | | | |
| TMDSCNCD2800137.syscfg.json | 22,030 | 7/11/2024 3:10:23 PM | | | |
| TMDSCNCD2800157.syscfg.json | 21,905 | 7/11/2024 3:10:23 PM | | | |
| TMDSFSIADAPEVM.syscfg.json | 1,906 | 7/11/2024 3:10:23 PM | | | |
| TMDXICE110.syscfg.json | 4,228 | 7/11/2024 3:10:23 PM | | | |
| | | | uninstallers | | 7/11/2024 9:59:07 AM |
| | | | C2000WareUpdater.exe | 7,188,861 | 4/8/2024 2:24:32 AM |
| license.html | 45,557 | 7/11/2024 3:09:21 PM | | | |