
## <Wave form>



## Question

Using LM5069 device, in case of start-up, it seems that FET-G doesn't operate normally, As the result, LM5069 can't output voltage. Especially, FET-G occurs spike voltage. (Red circle)

If you some advice, could you let us know? (For example, the constant of TIMER,,,)

About the circuit, please refer to next page.

## <The circuit>

## CONTROLL

