

Trouble (see attached figure)

>Only one phase operation not 12 phase(*)

>Outputting PWM signal is only one, no outputting other PWM signals

(*)Set each jumper10 to 13 1-2 short (12+0 operation)



Yellow : VOUT_A Green:PWM1 Red:PWM2 Other PWM