



BUC\_PWR\_RUN  
1=ENABLED  
0=DISABLED

Soft-start (TRK pin):  
 $C_{ss\ min.} = 1.3 \times 47nF \times (C_{out}/C_{out\ max}) =$   
 $= 1.3 \times 47nF \times (80\mu F/40\mu F) = 122nF$

