



set to AC or DC to test the circuit

AC LINE SENSING INPUT

Simulation parameters

```
.tran 0 .5 0 startup uic
.option fastaccess
.inc REF5030.LIB
```



--- C:\Users\r.volpini\Desktop\AC LINE_TMP.asc ---