




I am slightly confused on what this is in comparison to the power terminals. Why are the power terminals connected to VC0? and Same as above?

Recommend 1 uF caps here

Recommend 1 uF caps here

Purpose of this?

Connection to Charger PCB.

AWG14 Solder pad for LED load +.

BMS Enable signal from switch on Charger PCB.

Test points

Indicator LEDs

1	2	VC7	LD T
X21	X36	VC6	VSS T
1	2	VC6	LD B
X22	X37	VC5	BAT-
1	2	VC4	VDD T
X23	X34	VC3	VSS T
1	2	VC3	VDD B
X24	X35	VC2	BAT-
1	2	VC2	VDD T
X25	X29	VC1	VSS T
1	2	VC1	VDD B
X26	X30	VC0	BAT-
1	2	VC0	BMS_EN
X27	X31	VC0	PACK+
1	2	VC0	PACK-
X28	X32	VC0	CHG
			BAT-
			DSG
			BAT-
			SRP
			SRN

CHG	R38	D6	BAT-
DSG	R39	D7	BAT-
VDD T	R40	D8	VSS T
VDD B	R41	D9	BAT-
PACK+	R42	D10	PACK-
BMS_EN	R12	D11	BAT-

Title		
Size	Number	Revision
A3		
Date:	11.14.2025	Sheet of
File:	G:\Druzi\racunalnik\Architecture-BMS\BMS_Schematic	8