


1、BQ76940 did not respond.

2、BQ76940 occasionally experiences a lack of response in unexpected situations.

To activate BQ76940, it is necessary to disconnect the VCC of the MCU and manually trigger a high level on the TS1 pin through the button.



3、BQ76940 has responded.

