


EMI Jitter Pattern of Switching Frequency and Peak Current in UCC28700/1/2/3



Note: Valley switching and other system disturbances cause some deviation from "ideal" jitter behavior.