



This is my fix for the voltage transient. It shuts off the 5v shortly before it begins to drop out, and seems to reset the soft start mechanism. I'm still curious about the transient though.