

Figure 1 – PWMmaster (blue) PWAMAslave (green) and SYNC (purple) when control card is inserted into power plate and supplied from lab source at multiple supply turn on and turn off. After supply reset shift takes one of three values: 0, 90 (the rarest case), 180 degrees




Figure 2 – the rarest case (correct synchronization) in another time scale