


LM66100 ST PinP-SPICE ISSUE



Simulation shows ST Pin never floats to +5v. Also, VOUT never goes to +5V because U4 MOSFET is still ON

