


- **Package Analysis:**

- **External Package Examination:**

Optical inspection was performed on returned units. Flash metal and abnormal PI were observed on both units.








Figure 1. Optical pictures of package surface



- **Observation:**

Optical inspection was performed on returned units. Flash metal and abnormal PI were observed on both units.