
UCC28513 questions, Alex W., 11/17/2022


- The boost stage design is based on UCC28513. The PFC stage works well up to 200-220Vac input. Above this voltage range there are significant distortions at the points where sinusoidal input voltage reaches to its positive and negative peaks
- Output voltage is 385Vac
- Input voltage range is 85-264Vac; 50/60Hz
- The load on DC link output is 120W max
- Boost stage switching frequency is 277kHz
- Verified that the Vcc aux supply and Vref are stable
- Observed that the AC ripple on DC link goes up at around 200Vac but not sure it this is the reason or the result
- Observed that the duty cycle is about 70% at the peak sine wave at 85Vac but drops down to ~15% at the peaks of 220Vac at which point I start get distortions on the input current.
- The provided test results are at ~30W output power. It was observed that changing the load did not affect the behavior at around 220Vac.

# <u>Questions:</u>


- 1. Based on the design values, what could potentially cause the distortions at the peak of sine waves at and above ~ 200Vac?
- 2. Fig. 36 on data sheet talks about max capacitance vs min duty cycle. What capacitor is referred in Fig 36?




RefDes on data sheet	RefDes in design	values	
R1	R47+R50	766K	
R2	R43	0.22	
R8/R12	R4/R9	3.16K	
R3	R44+R49	1124K	
R4	R60	22.1k	
C1	C32	150uF	
L1	L2	660uH	
R13	R10	15.8K	
C6	C6	680pF	
С7	C8	150pF	
R15	R11	30.1K	
C8	С9	4.7uF	
C10	C1	1.5uF	
C11	C2	150nF	
R21	R1	48.7K	
R14	R13	10K	
R7	R5	1.18K	
С9	C4	1uF	





RefDes on data sheet	RefDes in design	values	
R8/R12	R4/R9	3.16K	
R13	R10	15.8K	
C6	C6	680pF	
R15 R11		30.1K	








# No distortions at 200Vac input, displacement between current and voltage is probably caused by the input capacitors on EMI filter













Input voltage ( <u>Vrms</u> )	Vff on pin19 w/ DiffProbe (Vdc)	Vaout on pin1 w/ DVM (Vdc)	0 < i (t) < 500 A
85	1.80	2.000	$0 \le i_{IAC}(t) \le 500 \mu\text{A},$
120	2.56	1.977	$0 \leq V_{VAOUT}(t) \leq 5 V,$
150	3.24	1.967	$1.4 \text{ V} \le \text{V}_{\text{VFF}} \le \text{V}_{\text{VREF}} - 1.4 \text{ V}$
200	4.38	1.933	VFF VICEF
220	4.81	1.900	





- Vff increases proportionally and <u>Vaout</u> drops inversely as Vac increases.
- Vaout seems to start low at 2V and not varying within its full range of 0-5V

12

65









### UCC28513 questions to TI, Alex W., 11/17/2022

At the peak of sinewaves when distortion starts, the duty cycle of boost MOSFET is about 15%




# UCC28513 questions to TI, Alex W., 11/17/2022

#### At the peak of sinewaves at 120Vac, the duty cycle of boost MOSFET is about 54%




# UCC28513 questions to TI, Alex W., 11/17/2022


#### At 220Vac when distortions starts, the rectified input voltage (used for Vff) is shown below





Referring to Fig 36 in the data sheet of UCC28513DW, what specific capacitor controls the min duty cycle?





Note: The capacitor on Isense2 affects the min duty cycle on GATE2 output, PFC is on GATE1 output
















RefDes on data sheet	RefDes in design	values	Values on 12/11/2022	Changes made
R1	R47+R50	766K		on 12/11 are
R2	R43	0.22	0.44	highlighted
R8/R12	R4/R9	3.16K	2.74K	
R3	R44+R49	1124K		
R4	R60	22.1k		
C1	C32	150uF		
L1	L2	660uH		
R13	R10	15.8K	55K (56K//3.3Meg)	Also tried 15.8k
C6	C6	680pF	233pF (200p//33p)	
C7	C8	150pF	33pF	
R15	R11	30.1K		
C8	С9	4.7uF		
C10	C1	1.5uF		
C11	C2	150nF		
R21	R1	48.7K		
R14	R13	10K		
R7	R5	1.18K	1.50K (3.3K//2.74K)	
С9	C4	1uF		25












There are only two current probes at the moment:


Ch1: Fluke 80i-110S has limited bandwidth and is used to measure 60Hz input current only.


Ch4: Rogowski probe, CWTUM-015-B, is used to measure the high frequency switching ripple only.

In addition, a  $100m\Omega$  and  $20m\Omega$  sense resistor was connected in series with inductor and the voltage across the resistor was measured with a differential probe. However, doing so resulted in further instability and distortion and therefore abandoned.










Ch1: Current probe is Fluke 80i-110S, which has limited bandwidth and is used to measure 60Hz input current

Ch4: Current probe is Rogowski CWTUM-015-B, which can measure high frequency only.


At the peak of 85Vac input voltage and ~25W external load, the instantaneous value of input voltage is 132V, peak input current is 660mA, duty cycle = 64.28%



Ch1: Current probe is Fluke 80i-110S, which has limited bandwidth and is used to measure 60Hz input current

Ch4: Current probe is Rogowski CWTUM-015-B, which can measure high frequency only.


At the peak of 220Vac input voltage and ~25W external load, the instantaneous value of input voltage is 312V, peak input current is ~300mA (location B), duty cycle is about 14.2%



37


# Measuring inductor current vs gate voltages, 12/25 Ch1: Fluke 80i-110S, which has limited bandwidth Ch4: Tek TCPA300 w/ TCP312 Current probe

At 85Vac input voltage and ~25W external load, no major distortions observed




# Measuring inductor current vs gate voltages, 12/25 Ch1: Fluke 80i-110S, which has limited bandwidth Ch4: Tek TCPA300 w/ TCP312 Current probe

At 85Vac input voltage and ~25W external load, no major distortions observed




Ch1: Fluke 80i-110S, which has limited bandwidth Ch4: Tek TCPA300 w/ TCP312 Current probe

At ~230Vac input voltage and ~25W external load, distortions observed. See next slides for location A, B details



Ch1: Fluke 80i-110S, which has limited bandwidth Ch4: Tek TCPA300 w/ TCP312 Current probe

At ~230Vac input voltage and ~25W external load, distortions observed.




Ch1: Fluke 80i-110S, which has limited bandwidth

Ch4: Tek TCPA300 w/ TCP312 Current probe

At ~230Vac input voltage and ~25W external load, distortions observed.

#### Location B details:

At the positive peaks of input voltage, the switching frequency is reduced to about ½ and this results in "flat top" on the current waveform. After that the switching frequency is raised and around that time the current surge is observed




Ch1: Fluke 80i-110S, which has limited bandwidth

Ch4: Tek TCPA300 w/ TCP312 Current probe

At ~230Vac input voltage and ~25W external load, distortions observed.

#### Location B details:

At the positive peaks of input voltage, the switching frequency is reduced to about ½ and this results in "flat top" on the current waveform. After that the switching frequency is raised and around that time the current surge is observed




Ch1: Fluke 80i-110S, which has limited bandwidth

Ch4: Tek TCPA300 w/ TCP312 Current probe

At ~230Vac input voltage and ~25W external load, distortions observed.

### At 230Vac input, 25W external load, the view of locations A (negative peak) and location B (positive peak)




Ch1: Fluke 80i-110S, which has limited bandwidth

Ch4: Tek TCPA300 w/ TCP312 Current probe

At ~230Vac input voltage and ~25W external load, distortions observed.

#### Location A: Current probe on Ch1 has low BW and is used to measure input current only.




Ch1: Fluke 80i-110S, which has limited bandwidth

Ch4: Tek TCPA300 w/ TCP312 Current probe

At ~230Vac input voltage and ~25W external load, distortions observed.

#### There is a 68nF cap after the rectifier. It is increased to 2x68=136nF, did not observe any improvements




Ch1: Fluke 80i-110S, which has limited bandwidth

Ch4: Tek TCPA300 w/ TCP312 Current probe

At ~230Vac input voltage and ~25W external load, distortions observed.


#### There is a 68nF cap after the rectifier. It is increased to 2x68=136nF, did not observe any improvements



Ch1: Fluke 80i-110S, which has limited bandwidth

Ch4: Tek TCPA300 w/ TCP312 Current probe

At ~230Vac input voltage and ~25W external load, distortions observed.



Ch1: Fluke 80i-110S, which has limited bandwidth

Ch4: Tek TCPA300 w/ TCP312 Current probe


At ~230Vac input voltage and ~25W external load, distortions observed.



Ch1: Fluke 80i-110S, which has limited bandwidth

Ch4: Tek TCPA300 w/ TCP312 Current probe


At ~230Vac input voltage and ~25W external load, distortions observed.



Ch1: Fluke 80i-110S, which has limited bandwidth

Ch4: Tek TCPA300 w/ TCP312 Current probe


At ~230Vac input voltage and ~25W external load, distortions observed.



Ch1: Fluke 80i-110S, which has limited bandwidth

Ch4: Tek TCPA300 w/ TCP312 Current probe


At ~230Vac input voltage and ~25W external load, distortions observed.



Ch1: Fluke 80i-110S, which has limited bandwidth

Ch4: Tek TCPA300 w/ TCP312 Current probe

At ~230Vac input voltage and ~25W external load, distortions observed.



Ch1: Fluke 80i-110S, which has limited bandwidth Ch4: Tek TCPA300 w/ TCP312 Current probe At ~230Vac input voltage and ~25W external load, distortions observed.

## **Observations:**

- 1) Location A: While the supply voltage ramps up toward the negative peak, the switching frequency is reduced significantly and then MOSFET shuts down for a while at the negative peak. It seems like the inductor current is relatively small and this may not be current limit initiated turn off.
- 2) Location B: While the supply voltage ramps up toward the positive peak, the switching frequency is reduced by about 50%. It is observed this corresponds to "flat top" on supply current. At around the peak of supply voltage, the switching frequency suddenly snaps back to normal frequency and this corresponds to surge in peak of the supply voltage. It is not clear if this phenomenon is caused by activation of current limit.
- 3) Adding an other 68nF cap after rectifier did not improve the issue
- 4) Adding 100nF cap across R5 (R7 on data sheet) did not improve the issue

РСВ	RefDes on datasheet	RefDes in design	12/11/2022 Fci=44kHz, Gci=5.6	12/25/2022 Fci=11kHz, Gci=1.6
PSB- 04	R1	R47, R50	383K	383K
	R2	R43	0.44	0.44
	L1	L2	660uH	660uH
PFC- 03	R8, R12	R4, R9	2.74K	2.74К
	R13	R10	15.8K	4.7K
	C6	C6	233pF (200p//33p)	3.3n
	С7	C8	33pF	150pF
	R15	R11	30.1K	30.1K
	C8	С9	4.7uF	4.7uF
	C10	C1	1.5uF	1.5uF
	C11	C2	150nF	150nF
	R21	R1	48.7K	48.7K
	R14	R13	10K	10К
	R7	R5	1.50K (3.3K//2.74K) +100pF	1.50K (3.3K//2.74K <b>) + 100pF</b>
	С9	C4	1uF	1uF

55

Ch1: Fluke 80i-110S, which has limited bandwidth

Ch4: Tek TCPA300 w/ TCP312 Current probe

Per changes listed on page 55

At ~85Vac input voltage and ~25W external load, no major distortions observed




Ch1: Fluke 80i-110S, which has limited bandwidth

Ch4: Tek TCPA300 w/ TCP312 Current probe

Per changes listed on page 55

At ~230Vac input voltage and ~25W external load, major distortions observed




Ch1: Fluke 80i-110S, which has limited bandwidth

Ch4: Tek TCPA300 w/ TCP312 Current probe

Per changes listed on page 55

At ~230Vac input voltage and ~25W external load, major distortions observed Investigating the effect of C46 on input current distortions




Ch1: Fluke 80i-110S, which has limited bandwidth

Ch4: Tek TCPA300 w/ TCP312 Current probe

Per changes listed on page 55

At 90Vac input voltage, <u>no C46</u>, no major distortions observed Ch4: Tek TCPA300, Ch1: Fluke 80i-110S




Ch1: Fluke 80i-110S, which has limited bandwidth

Ch4: Tek TCPA300 w/ TCP312 Current probe

Per changes listed on page 55

At ~100Vac input voltage, <u>no C46</u>, distortions started, notice the current surge from location A to B Ch4: Tek TCPA300, Ch1: Fluke 80i-110S




Ch1: Fluke 80i-110S, which has limited bandwidth

Ch4: Tek TCPA300 w/ TCP312 Current probe

Per changes listed on page 55

At ~100Vac input voltage, <u>no C46</u>, distortions started Ch4: Tek TCPA300, Ch1: Fluke 80i-110S




Ch1: Fluke 80i-110S, which has limited bandwidth

Ch4: Tek TCPA300 w/ TCP312 Current probe

Per changes listed on page 55

At ~85Vac input voltage, <u>C46=100nF</u>, no major distortions Ch4: Tek TCPA300, Ch1: Fluke 80i-110S




Ch1: Fluke 80i-110S, which has limited bandwidth

Ch4: Tek TCPA300 w/ TCP312 Current probe

Per changes listed on page 55

At ~140Vac input voltage, <u>C46=100nF</u>, no major distortions Ch4: Tek TCPA300, Ch1: Fluke 80i-110S




Ch1: Fluke 80i-110S, which has limited bandwidth

Ch4: Tek TCPA300 w/ TCP312 Current probe

Per changes listed on page 55

At ~230Vac input voltage, <u>C46=100nF</u>, symmetric distortions show up on peaks of voltage waveform Ch4: Tek TCPA300, Ch1: Fluke 80i-110S




Ch1: Fluke 80i-110S, which has limited bandwidth

Ch4: Tek TCPA300 w/ TCP312 Current probe

Per changes listed on page 55

At ~230Vac input voltage, <u>C46=100nF</u>, location A; ON times gets very small & pulses start to drop Ch4: Tek TCPA300, Ch1: Fluke 80i-110S



Ch1: Fluke 80i-110S, which has limited bandwidth

Ch4: Tek TCPA300 w/ TCP312 Current probe

Per changes listed on page 55

At ~230Vac input voltage, <u>C46=100nF</u>, location A; ON times gets very small & pulses start to drop Ch4: Tek TCPA300, Ch1: Fluke 80i-110S



Measuring inductor current vs gate voltages, 12/28 Ch1: Fluke 80i-110S, which has limited bandwidth Ch4: Tek TCPA300 w/ TCP312 Current probe Per changes listed on page 55

#### Conclusions on 12/28:

- 1) Removing the 47nF cap across the sense resistor made the issue worse that the current became more unstable and distortions started even at low voltages of ~100Vac
- 2) Replacing the capacitor across the sense resistor (C46) with 100nF, did not improve the problem that the current waveform was stable up to ~ 230Vac and distortions started above this voltage, as it was the case with C46=47nF
- 3) Referring to location A; it appears that the duty cycle gets very small and even some pulses were dropped even though the current through the inductor does not appear to be the max. This suggests that the event is not initiated by peak current limit
- 4) Referring to location B; at this point no pulse dropping is observed. On the contrary, the duty-cycle increases which results in surge in inductor current.