



Question

I verified it with the circuit on the right.
Inrush current: 350mA (peak) 4ms

became.

Is this rush current a problem for the IC?

100mA/div

20ms/div



In addition, the data sheet states, "The TLV713 also provides inrush current control during device power up and enabling. There is.

This time, the inrush current is large. Why?