


Vin = +24V, Vopos = +15V, Voneg = -15V, SYNC = 500kHz, 3.3V



At point B, it operates with an offset of about 1V.
The RT / CLK low threshold is not met.
How can customer improve this?

