




Red voltages are readings while converter "Frozen" one time.
 Checked with oscilloscope. Voltages are stable. No sign of oscillation.

Only change from Webbench design is the diode I added to bypass converter.
 This is intended to bypass converter when 12V is input ... could this somehow cause problem???