



TPS61185 Vin transient response test circuit



TPS61185 Vin transient response



1. Why does the IC disable current sink and stop switching?
2. What is the condition of re-start switching?