

In comparison with OK_IC, ON / OFF timing of the gate is abnormal in the case of NG_IC.

Why is this behavior?

Please tell me the possible causes.