



bq24090EVM



14 Sep 2016
11:28:27



Vout is increased due to additional resistor on BAT+.

