





If I run the BAT script file directly, it does not automatically generate the package. The following error occurs.




All files running scripts on ti's official website will report an error. Later, I pointed the library path to the downloaded folder and manually ran SCR script files to solve the problem.





In conclusion, your script can not run, you need to manually run, this is my own repeated attempts to solve the problem later .



| 名称 | 修改日期 | 类型 | 大小 |
|-------------------------|------------------|--------------------|------|
| 2021-08-29_08-15-28.bat | 2021-08-29 8:15 | Windows 批处理... | 2 K |
| allegro.jrl | 2021-08-29 16:57 | JRL 文件 | 6 K |
| allegro.jrl,1 | 2021-08-29 16:18 | JRL,1 文件 | 9 K |
| batch_drc.log | 2021-08-29 16:18 | 文本文档 | 2 K |
| builder.ile | 2020-11-20 19:34 | ILE 文件 | 49 K |
| builder.scr.txt | 2021-08-29 16:16 | 文本文档 | 1 K |
| CSD87381PT.txt | 2021-08-29 8:15 | 文本文档 | 1 K |
| ImportGuide.html | 2021-08-29 8:15 | Microsoft Edge ... | 9 K |
| master.tag | 2021-08-29 16:18 | TAG 文件 | 1 K |
| MPC5_TEX.dra | 2021-08-29 16:18 | DRA 文件 | 73 K |
| mpc5_tex.log | 2021-08-29 16:18 | 文本文档 | 1 K |
| mpc5_tex.psm | 2021-08-29 16:18 | PSM 文件 | 13 K |
| MPC5_TEX.xml | 2021-08-29 8:15 | XML 文档 | 10 K |
| rx10y98d0t.pad | 2021-08-29 16:18 | PAD 文件 | 5 K |
| rx13y13d0t.pad | 2021-08-29 16:18 | PAD 文件 | 5 K |
| rx16y28d0t.pad | 2021-08-29 16:18 | PAD 文件 | 5 K |
| rx36y28d0t.pad | 2021-08-29 16:18 | PAD 文件 | 5 K |