

The measurement is most likely noise instead of the real voltage. Even if it is real, the part should be able to handle -2.8V for less than 10ns.