

Hi Team,

We have the below observations based on TI feedback.

- 1) We think so TI has marked Rx & Fb/Tx impedance in reverse way. It should be like Rx is 50ohm and Fb/Tx are 100ohm.

**Serkan Tokgoz** 15 hours ago

TI_Intellectual 950 points

Hi Pavan,

The reason is that Rx is 100ohm and Fb/Tx are 50ohm. For the latest layout and schematics, please review attached files.

[DC221C_AFE7769DEVM.brd](#)

[DC221C1_AFE7769D-35EVM-SCH.pdf](#)

Thanks

- 2) We observed various DRC warning on the Rx side. Please review these warning. Highlighted few for your reference.

