


<Noise on COM pin>



■ Question ■

On above figure, if the noise which is over 0.5V/us gradient is added to COM pin, does the device cause damage to the internal gate driving circuitry?

- Voltage Gradient : 0.5V/us over
- The noise voltage difference : 5~6V