



- ① 1.5V : After B1LS turns off(Cause unknown(noise))
- ② 0.3V : It occurs synchronized with Aout1, Aout2 falling.

The customer checked with some cases.

