


<In case of Lead time=1.12ms>



After abnormal speed occurred, DRV10983 stopped and then VCC was more than absolute maximum rating(30V).

Changing point which is from open loop to closed loop

10 Oct 2019
15:12:38