

M1	M0	STEP MODE
0	0	Full step with 71% current
1	0	1/2 step
1	1	1/4 step
0	1	1/16 step
0	Z	1/8 step
1	Z	Non-circular 1/2 step

DECAY	Increasing steps	Decreasing steps
100 mV Can be tied to GND	Slow decay	Mixed decay: 30% fast
300 mV 15kohm to GND	Mixed decay: 30% fast	Mixed decay: 30% fast
1 V 45kohm to GND	AutoTune Ripple Control	AutoTune Ripple Control
2.9 V Can be tied to DVDD	AutoTune Dynamic Decay	AutoTune Dynamic Decay

TORQUE	CURRENT SCALAR
0	100%
Z	75%
1	50%

