



Layout note:
Bottom pad
connection is critical

CONNECTIONS
TO CPU BOARD

Title PCA DRIVER, KLS 2.0		
Size B	Document Number 9703-200	Rev <Rev Code
Date: Monday, October 29, 2018	Sheet 2 of 2	1