

Assign IC Component Model

Reference designator: U2

Select model

Libraries:

- t66a.ibs
- t67a.ibs
- t67m.ibs
- t68m.ibs
- t79m.ibs
- t85a.ibs
- TOSHIBA\_mod.ibs
- ts5a3166.ibs
- u67a.ibs
- u68a.ibs

Library Path...

Arrange Pins

	Visible	Signal
1	<input checked="" type="checkbox"/>	A1
2	<input checked="" type="checkbox"/>	B1
3	<input checked="" type="checkbox"/>	Y1
4	<input checked="" type="checkbox"/>	A2
5	<input checked="" type="checkbox"/>	B2
6	<input checked="" type="checkbox"/>	Y2
7	<input checked="" type="checkbox"/>	GND
8	<input checked="" type="checkbox"/>	Y3
9	<input checked="" type="checkbox"/>	A3

Auto-Place Ports:

Hint  
Use the Manage Assigned Models dialog box (Models > Manage Assigned Models) to assign I/O buffer direction, Model Selectors, Stimuli and more.

Model Loading Error

Errors while loading model(s)

Y:\LS\Hardware\Simulation\SI\ts5a3166.ibs:  
Warning : Model Id has no library.  
Warning : at line 125 in file Y:\LS\Hardware\Simulation\SI\ts5a3166.ibs :  
Error : at line 136 in file Y:\LS\Hardware\Simulation\SI\ts5a3166.ibs :  
Error : ?  
Error : at line 6904 in file Y:\LS\Hardware\Simulation\SI\ts5a3166.ibs :  
Error : Parse failed on file Y:\LS\Hardware\Simulation\SI\ts5a3166.ibs

2

not-assigned

Untitled - Notepad

File Edit Format View Help

Y:\LS\Hardware\Simulation\SI\ts5a3166.ibs:  
Warning : Model Id has no library.  
Warning : at line 125 in file Y:\LS\Hardware\Simulation\SI\ts5a3166.ibs : only the first combination from the [Series Switch Groups] will be used.  
Error : at line 136 in file Y:\LS\Hardware\Simulation\SI\ts5a3166.ibs : component TS5A3166\_DBV has duplicate series pin mapping entries.  
Error : ?  
Error : at line 6904 in file Y:\LS\Hardware\Simulation\SI\ts5a3166.ibs : syntax error, unexpected identoken, expecting \$end  
Error : Parse failed on file Y:\LS\Hardware\Simulation\SI\ts5a3166.ibs.

output  
[INFO]Opening Schematic: Y:\LS\Hardware\Simulation\SI\Analog\_Switch.fs