







Reduced inrush current after removing 10uF on REG_CAP pins.



Removed 10uFx2 on REG_CAP 1/2.