


INPUT REFERENCE 1



Input jumpers
Connect center pin to
* 0.9V for 1.8V LVDS
* 1.2V for LVDS
* GND for HCSL

INPUT REFERENCE 2




Figure 5. Schematic (3 of 6)