



PPC3 – Environment Variables Fix

Applications Engineering – Low Power Audio & Actuators

Update Environment Variables – 1

- Open **File Explorer**
- Right-click on **This PC** and **Properties**
- Select **Advanced system settings**



Update Environment Variables – 2

- In **Advanced** tab, select **Environment Variables**
- Under **System variables** look for **Path** and double click on it

The image shows two overlapping Windows dialog boxes. The left box is 'System Properties' with the 'Advanced' tab selected. A red arrow points from the 'Advanced' tab to the 'Environment Variables...' button at the bottom. The right box is 'Environment Variables' with the 'System variables' section expanded. A red arrow points from the 'Path' variable in the 'System variables' list to the 'Edit...' button.

System Properties - Advanced Tab

Computer Name | Hardware | **Advanced** | System Protection | Remote

You must be logged on as an Administrator to make most of these changes.

Performance
Visual effects, processor scheduling, memory usage, and virtual memory
Settings...

User Profiles
Desktop settings related to your sign-in
Settings...

Startup and Recovery
System startup, system failure, and debugging information
Settings...

Environment Variables...

OK | Cancel | Apply

Environment Variables

User variables for x0229846

Variable	Value
OneDrive	C:\Users\x0229846\OneDrive
Path	C:\Users\x0229846\AppData\Local\Microsoft\WindowsApps;
TEMP	C:\Users\x0229846\AppData\Local\Temp
TMP	C:\Users\x0229846\AppData\Local\Temp

New... | Edit... | Delete

System variables

Variable	Value
ComSpec	C:\windows\system32\cmd.exe
DriverData	C:\Windows\System32\Drivers\DriverData
NIEXTCCOMPILERSUPP	C:\Program Files (x86)\National Instruments\Shared\ExternalCompi...
NUMBER_OF_PROCESSORS	8
OS	Windows_NT
Path	C:\windows\system32;C:\windows;C:\windows\System32\Wbem;C...
PATHEXT	.COM;.EXE;.BAT;.CMD;.VBS;.VBE;.JS;.JSE;.WSF;.WSH;.MSC

New... | Edit... | Delete

OK | Cancel

Update Environment Variables – 1

- Click on **New** and add the following: C:\Program Files (x86)\MATLAB\MATLAB Compiler Runtime\v716\runtime\win32
- Click **OK** and close all other windows

