



conversion many times




# 1st time conversion (enlarge)

correction 24clk



BUSY High to Low at the DIN first pulse


## 2nd time conversion (enlarge)



BUSY High to Low at the /CS High to Low

1st time conversion DOUT(enlarge)


DOUT output some data  
while send DIN



Sometime, BUSY High to Low at the /CS High to Low

## 2nd time conversion DOUT(enlarge)

DOUT output some data  
while send DIN



Sometime, BUSY High to Low at the /CS High to Low