


ZZ4 ■These assemblies must comply with workmanship standards IPC-A-610 Class 2, unless otherwise specified.

ZZ3 ■These assemblies must be clean and free from flux and all contaminants. Use of no clean flux is not acceptable.

ZZ2 ■These assemblies are ESD sensitive, ESD precautions shall be observed.

ZZ1 ■Install label in silkscreened box after final wash. Text shall be 8 pt font. Text shall be per the Label Table in the PDF schematic.



COMPONENTS MARKED 'DNP' SHOULD NOT BE POPULATED.
ASSEMBLY VARIANT: 001

PCB VIEWED FROM TOP SIDE	BOARD #: AMPS214	REV: A	SUN REV: Not in version control
PLOT NAME = Top Assembly Drawing	GENERATED : 11/15/2023 4:03:01 PM	TEXAS INSTRUMENTS	



COMPONENTS MARKED 'DNP' SHOULD NOT BE POPULATED.
ASSEMBLY VARIANT: 001

PCB VIEWED FROM BOTTOM SIDE	BOARD #: AMPS214	REV: A	SUN REV: Not in version control
PLOT NAME = Bottom Assembly Drawing	GENERATED : 11/15/2023 4:03:02 PM		TEXAS INSTRUMENTS