


1. I plugin the USB cable and start the GUI program in about 1 minutes, the device connected
I read the temperature information, I usually got wrong detector temperature (sometimes very huge, some times is 0)

Sensors		Sensors	
Battery Voltage	0.0 V	Battery Voltage	0.0 V
Ambient Temp	-0.01 C	Ambient Temp	-0.01 C
Detector Temp	338821.16 C	Detector Temp	0.00 C
Humidity	31.03 %	Humidity	30.65 %
HDC Temp	26.48 C	HDC Temp	26.77 C
Tiva Temp	30.69 C	Tiva Temp	31.06 C
Photodetector	0	Photodetector	0

2. Then I disable this Hibernate Mode button.



3. My firmware version is:



4. And then I exit this GUI, and re-plugin the device's USB cable.

5. Wait for about 10 minutes, and start the GUI program again. It cannot find the device.

