

MSP430F5529 Target Board - Hardware Changes Required

	<u>Component</u>	<u>Correct Value</u>	<u>Package</u>	<u>Manu Part Num</u>	<u>Digikey Part Number</u>	
1	Populate pull down resistor at DP	R11	1M Ω (+/-5%)	SMD - 0603	ERJ-3GEYJ105V	P1.0MGCT-ND
2	Change the XT2 Load caps	C3	47pF	SMD - 0805	C0805C470J5GACTU	399-1117-1-ND
		C4	47pF	SMD - 0805	C0805C470J5GACTU	399-1117-1-ND