



- Notes:
- Changes to Rev B.
 - 1. Removed R2
 - 2. Removed C3
 - 3. Changed Connection for VCC and Driver Circuit
 - 4. Removed R16
 - 5. Removed C12
 - 6. Added R100 - 324ohm
 - 7. Changed D2 to a BAT54
 - 8. Changed C9 = 0.047uF

Texas Instruments

Title TL5001 Flyback		
Size B	Number PMP1637	Rev B
Date 11-30-05	Drawn by R Taylor	
Filename PMP1637_REVB_v2.SCH		Sheet 1 of 1