

These are VID interface waveform of the EVM GUI software.

In LM10011 VID interface timing characteristic of datasheet P5, t1 and t3 is max 1us.

I think we have to wait more than 1us between VID signal change and VIDS signal change.

However there is no wait time on VID interface waveform of EVM GUI.

What can I think about this?

Is the timing of EVM GUI wrong? Could you tell me your opinion?